

# 2Touch™ Calibration

1. Plug Laptop into USB, RGB (projector) and audio connectors



2. Turn on Projector. Check input.




3. Ensure laptop is displayed on projector



4. Press Scroll-lock [ScrLk] six times



5. Use your finger or a pen to touch the point of the cursor for 3-5 seconds in each of the 4 positions.



Audio Visual Systems  
Ph: 9457 4800

